




993-0618

Seite/Page 1 / 3

Bild-Nr Fig Fig Fig Fig Bild nr	ET-Nr Part-No No. de Piece No. de Pieza No. del Pezzo Detalj nr	Stückzahl Qty Qte Ctd Qta Antal	Gegenstand Description Designation Descripcion Designazione Benaemning	
10		1	Deckel	Cover
30		1	Dichtung	Gasket
40		8	Skt.-Schraube	Hexagon screw
41		8	Federscheibe	Spring washer
80		1	Mutter	Nut
90		1	Skt.-Mutter	Hexagon nut
100		1	Stift	Pin
110		1	Nutring	U-ring
120		1	Scheibe A = 3,00 mm	Washer
130		1	Bolzen	Pin
140		1	Druckfeder	Compr. spring
150		1	Kugel	Ball
160		1	Verschlußschraube	Screw plug
164		1	Scheibe A = 2,60 mm	Washer
170		1	Entlüfter	Breather
200		2	Bolzen	Pin
220		2	Buchse	Bushing
230		1	Scheibe	Washer
-		nB	Scheibe A = 3,00 mm	Washer
-		nB	Scheibe A = 2,30 mm	Washer
-		nB	Scheibe A = 2,60 mm	Washer
-		nB	Scheibe A = 2,40 mm	Washer
-		nB	Scheibe A = 2,20 mm	Washer
-		nB	Scheibe A = 2,00 mm	Washer
-		nB	Scheibe A = 1,80 mm	Washer
-		nB	Scheibe A = 1,60 mm	Washer
-		nB	Scheibe A = 1,40 mm	Washer
-		nB	Scheibe A = 1,20 mm	Washer
-		nB	Scheibe A = 1,00 mm	Washer
-		nB	Scheibe A = 0,80 mm	Washer
240	777 813 73	1	Schalter	Switch
460		1	Ring	Ring
-		nB	Ring A = 3,00 mm	Ring
-		nB	Ring A = 2,80 mm	Ring
-		nB	Ring A = 2,60 mm	Ring
-		nB	Ring A = 2,40 mm	Ring
-		nB	Ring A = 2,20 mm	Ring
-		nB	Ring A = 2,00 mm	Ring
-		nB	Ring A = 1,80 mm	Ring
-		nB	Ring A = 1,60 mm	Ring

Bild-Nr Fig Fig Fig Bild nr	ET-Nr Part-No No. de Piece No. de Pieza No. del Pezzo Detalj nr	Stückzahl Qty Qte Ctd Qta Antal	Gegenstand Description Designation Descripcion Designazione Benaemning	
-		nB	Ring A = 1,40 mm	Ring
-		nB	Ring A = 1,20 mm	Ring
-		nB	Ring A = 1,00 mm	Ring
-		nB	Ring A = 0,80 mm	Ring
500	420 029 12	1	Schalter	Switch
Ganganzeige Gear Indicator 993-0618 Seite/Page 3 / 3				