



90-2492

Bild-Nr Fig Fig Fig Fig Bild nr	ET-Nr Part-No No. de Piece No. de Pieza No. del Pezzo Detailj nr	Stückzahl Qty Qte Ctd Qta Antal		Gegenstand Description Designation Descripcion Designazione Benaemning
00	604 379 40	1	Rücklauffilter, kpl.	Return oil filter assy.
01	978 076 73	1	Deckel	Cover
02	978 077 73	1	Kopfteil	Head piece
03	302 463 99	4	Schraube	Bolt
-	509 850 98	1	Verschlussschraube	Plug
-	339 985 99	1	Dichtring	Seal ring
06	761 950 73	1	Ventil 2,5 bar	Valve
07	978 178 73	1	Filterrohr	Filter tube
08	978 177 73	2	Filterelement	Filter element
09	511 401 98	1	O-Ring	O-ring
10	511 200 98	1	O-Ring	O-ring
11	332 197 99	4	Mutter	Nut
12	343 186 99	4	Federscheibe	Elastic washer
13	988 712 00	1	Flachdichtung	Gasket
Rücklauffilter				90-2492
Return Oil Filter				Seite/Page 2/2