



907-2195

Seite/Page 1 / 2

Bild-Nr Fig Fig Fig Fig Bild nr	ET-Nr Part-No No. de Piece No. de Pieza No. del Pezzo Detalj nr	Stückzahl Qty Qte Ctd Qta Antal		Gegenstand Description Designation Descripcion Designazione Benaemning
00	589 958 40	1	Rückfahrsirene, kpl. best. aus Bild-Nr. 01-09	Warning buzzer for reverse motion assy. consist. of fig-nos: 01-09
01	412 573 40	1	Sirene	Warning buzzer
02	509 772 98	2	Zylinderschraube	Screw
03	509 860 98	2	Mutter	Nut
04	509 788 98	2	Zylinderschraube	Screw
05	509 870 98	2	Mutter	Nut
06	546 876 40	1	Halter	Retainer
07	369 198 40	-	Kabel	Cable
08	057 251 40	2	Steckhülse	Sleeve
09	270 200 40	2	Aderendhülse	Wire end ferrule

Rückfahrsirene
Warning Buzzer for Reverse Motion

907-2195

Seite/Page 2 / 2