



993-0508

Seite/Page 1 / 2

03.12.2010

Bild-Nr Fig Fig Fig Fig Bild nr	ET-Nr Part-No No. de Piece No. de Pieza No. del Pezzo Detalj nr	Stückzahl Qty Qte Ctd Qta Antal		Gegenstand Description Designation Descripcion Designazione Benaemning
--	000 141 12	1	Rücklauffilter, kpl.	Return filter, assy.
10	420 421 12	1	Filterelement	Element
12	502 186 98	1	O-Ring	O-ring
21		1	Kopf	Head
22	504 091 98	1	O-Ring	O-ring
23	421 497 12	1	Dichtung	Gasket
31	473 346 12	1	Deckel	Cover
32	504 091 98	1	O-Ring	O-ring
40		1	Gehäuse	Housing
50	421 496 12	1	Korb	Strainer
61		1	Verschlussschraube	Screw plug
62	000 157 98	1	O-Ring	O-ring
70	421 495 12	1	Reparatursatz	Repair kit

Rücklauffilter
Returnfilter

993-0508

Seite/Page 2 / 2